

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	
Engine check.	OR COMMANDING OFFICER'S REPORT: Investigating Officer	81
	Report	<u> </u>
NATURE OF ACCIDENT AND STAGE OF FLIGHT	DATE: 29-5-42	
hile ckecking engine a normal	approximposition: / / / / / / / //////////////////////	
vas made arter a circuit prior	to landing.	
it 400' a red flare was fired.	The pilot F.L. Taylor, C.C. (C.2825) No. 1 B & G Sah	ron.
pened the throttle to go arou	ind again and Jarvis, Ontario.	.001
caised the undercarriage. A/C	did notecommendations:	
sain altitude and the engine be	egan to splutter	
and vibrate. Aircraft forced	-B	
	landed with	
PRIMARY CAUSE: wheels ur.		
PRIMARY CAUSE: wheels up.	landed with Nil	
PRIMARY CAUSE: wheels up.		
PRIMARY CAUSE: wheels up.	<u> - 1                                  </u>	
wheels up.	Nil over-ride.	
wheels up.  'ailure of engine after using of the control of the co	<u> - 1                                  </u>	
wheels up.	Nil  Over-ride.  ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  Nil	
wheels up.  'ailure of engine after using of the control of the co	Nil  Over-ride.  ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  Nil  Conclusions of A.I.B.	
wheels up.  'ailure of engine after using of the control of the co	Nil  over-ride.  ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  Nil  Conclusions of A.I.B.  (1) Incorrect carburettor adjustment resulting in 1	loss
wheels up.  'ailure of engine after using of the control of the co	Nil  over-ride.  ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  Nil  Conclusions of A.I.B.  (1) Incorrect carburettor as justment resulting in 1  of power.	4
rimary cause: wheels up.	Nil  Over-ride.  ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  Nil  Conclusions of A.I.B.  (1) Incorrect carburettor adjustment resulting in 1  of power.  (2) Faulty ignition harness A" side. The two fault	, ts
wheels up.  'ailure of engine after using of the control of the co	Nil  Over-ride.  ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  Nil  Conclusions of A.I.B.  (1) Incorrect carburettor at justment resulting in 1 of power.  (2) Faulty ignition harness A" side. The two fault coupled together would result in rough running	ts and
PRIMARY CAUSE: wheels up.  Pailure of engine after using of the contribution of the co	Nil  Over-ride.  ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  Nil  Conclusions of A.I.B.  (1) Incorrect carburettor at justment resulting in 1 of power.  (2) Faulty ignition harness A" side. The two fault coupled together would result in rough running loss of power with a tendency towards cutting of the coupled together would result in rough running loss of power with a tendency towards cutting of the coupled together would result in rough running loss of power with a tendency towards cutting of the coupled together would result in rough running loss of power with a tendency towards cutting of the coupled together would result in rough running loss of power with a tendency towards cutting of the coupled together would result in rough running loss of power with a tendency towards cutting of the coupled together would result in rough running loss of power.	ts and
SECONDARY CAUSE: wheels up.  Sailure of engine after using of irrest did not climb.  7. FORCED APPING.  SECONDARY CAUSE OR CONTRIBUTING FACTOR  Aircraft forced landed with wi	Nil  Over-ride.  ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  Nil  Conclusions of A.I.B.  (1) Incorrect carburettor adjustment resulting in 1 of power.  (2) Faulty ignition harness A" side. The two fault coupled together would result in rough running loss of power with a tendency towards cutting of the excess load placed upon englished due to add to the excess load placed upon englished due to add to the excess load placed upon englished due to add to the excess load placed upon englished due to add to the excess load placed upon englished due to add to the excess load placed upon englished due to add to the excess load placed upon englished due to add to the excess load placed upon englished due to add to the excess load placed upon englished due to add to the excess load placed upon englished due to add the excess load placed upon englished due to add to the excess load place	ts and out tion
PRIMARY CAUSE: wheels up.  Pailure of engine after using of the contribution of the co	Nil  Over-ride.  ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  Nil  Conclusions of A.I.B.  (1) Incorrect carburettor adjustment resulting in 1 of power.  (2) Faulty ignition harness A" side. The two fault coupled together would result in rough running loss of power with a tendency towards cutting of the excess lose and placed up 150 of the excess lose and placed up 15	ts and out tion