	Ct NCC INCC ON THERS		AIRFRAME FAILURE  CAUSES OF ACCIDENTS					ENGINE FAILURE					
UNIT	1 0.T.U.	PLACE West end of					H.Q. FILE 7700-54-50						
A/C TYPE	<del>;otvillo, Qu</del> s		No.	<del>in Ae</del> ar-		RASH		SE	МE	DA	-	IGHT	1 I WED
-	Upprior ne TTD NAME			RANK NO. DUTY			INJUR				SERIOUS		SCELI
PE OF ENGINE	Tallace, T. V. DEV COT 1256054 P. W.1  CARD SERIAL NO.							D /	A V E O U S				
	EA/F No.	EXTENT		SERIAL No.	DATE	ļ	ног		ON TYPE		TOTAL		S Let
	oricale 5450	OF DAMAGE Serio	FORM 18	NO.		INST.	NIGHT			DUAL		LAST 6 MOS.	["[∃]/.&
ν <sub>α</sub> ο P•	Merlin AC 41	-47533 Ser	ous										I T
ğ E			<u> </u>				REPO	<u> </u>		LE	DA		

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER								
Testing sircraft.	OR COMMANDING OFFICER'S REPORT:								
Engine failure in circuit and aircraft belly landed on aerodrome.  The engine of a/c stopped while in flight near aerodrome and pilot did not have sufficient altitude to make proper landing on runway.  PRIMARY CAUSE: Engine failure due to lack of ceelant.	DATE: 5 Jan./43 INVESTIGATING OFFICER  COMPOSITION: F.O. S.V.Grisdale, #130 Squadron.  LB								
Thought that original rough running									
of engine caused by enew compaction in curb. air intake.	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER								
17. FORCED LAND.	An order has been issued for rigid "between flight" and "after run up" inspections of all Hurricane								
$f = f \cdot f$	radiators.								
SECONDARY CAUSE OR CONTRIBUTING FACTORS:  Landed with U/C retracted under cross wind conditions and landed in deep so  D6, ENGINE TROUBLE—  R.C.A.F. FORM L20 REQ. 1247 10M—15-11-41	CONCLUSIONS OF A.I.B.  Engine failed due to overheating, caused by lack s- of coolant. Another case of mechanic declaring now. engine serviceable w/o first having found cause of being declared unserviceable. (See Summary of accident Investigation No. 775)								