

)	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
)	Drogue Towing detail.	OR COMMANDING OFFICER'S REPORT:
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	INVESTIGATING OFFICER'S REPORT
)	Aircraft seen to carry out nermal	COMPOSITION: F S/AUP/ES/NA/NK/I
)	landing on water approximately 400	
)	yards from shore and sank immediate ly.	
)	-5 -	RECOMMENDATIONS:
)		
)	PRIMARY CAUSE: ENGINE FAILURE WHEN A/C TOO PAR FROM SHORE	
)	TO GLIDE TO LAND.	
))	(17)	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER CONCLUSIONS OF A. I. B.
	17. FORCED KANDING	(1) Due to Engine Failing when A/C too Far from shore to GLIDE IN (2) Engine Failed due to Partial Seizure of Some of the Exhaust
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:	VALVES AND MAGNETO DEFECTS (3) MAGNETO POINTS WERE LAST ADJUSTED ON 10 DEC./42, 6 DAYS BEFORE, AFTER DIFFICULTY IN STARTING ENGINE. THE CONTACT BREAKER SHOULD NOT HAVE REDUCED TO .007" IN 5 HRS.
)	120/	& 40 MINS. RUNNING. RECORDED BY DATE
)	26. ENGINETROUBLE - ACCIDENT RIGISIE. FORM LEG. 1247 10M-15-11-41	CHECKED BY DATE
)		