| A/C | PILOT OTHERS | AIRFRAME FAILURE | | | | | Althred (16) | | | | | |
|--------------|-----------------------------------|------------------|--|----------|------------|-------|-----------------|-------------|------|---------------|-----------------|--|
| PE OF A | UNIT 128 Sqn. COM. Sydney, N.S. E | P. | PLACE Near Whycocomagh 60 mi. WSW of aerodrom | | | h | DATE] | 30 | | | | |
| ۲. | A/C TYPE Hurricane IIB | N | 5465 | ļ s | · B | • | χ | ME | D/ | X | NIGHT S | |
| | NAME RA | ANK | No. | DUTY | | A 3 U | RIES | RIES | | SERIC | O A C S C C C A | |
| PE OF ENGINE | Dack, D.B. | F/S R10905 | | F U • | Slightly | | | | | CAR SERIAL | D NO. | |
| <u>≻</u> | TYPE A/F NO. EXTENT OF DAMAGE | REPO | PORT SERIAL | DATE | НО | | URS FLOWN BY PI | | | | 111/ | |
| | Hurr'n IIB 5465 | FC | ORM No. | | INST. | NIGHT | ON T | YPE solo | DUAL | FAL solo | 6 MOS. 1 4 | |
| SORY | Merline #SAF41- 47539/A3052 | - | | | | | | | | | G E V | |
| TEGO | SIGNAL NO. & DATE UNIT NO. & DA | <u> </u> | COM | No. & DA | TE | REPO | DT I | FI | LE | T D | ATE 7 5 | |

DUTY ON WHICH ENGAGED: COURT OF INQUIRY, INVESTIGATING OF Search for missing Hudson. OR COMMANDING OFFICER'S REPO NATURE OF ACCIDENT AND STAGE OF FLIGHT: DATE: Engine failure - crash landed COMPOSITION: in clearing. Although fuel was in the tanks fuel pressure zero and Primer pump did not work. RECOMMENDATIONS: To again warn pilot to constantly check fuel supply most especially when flying at low levels and prior PRIMARY CAUSE: to aerobatics and steep turns. This point will be 54. Engine failure convered in Pilots Handling Notes. **ACTION TAKEN:** (A) DISCIPLINARY (B) TECHNICAL (C) OTHER SUMMARY OF ACCIDENT #1017 Examination of the a/c showed that the shut off cock between the reserve tank and selector valve was very nearly in the closed position and that only a small amount of f fuel flowed from it, not a sufficient amount to keep the e gine going. Thre reserve tank was full. The shut off c SECONDARY CAUSE OR CONTRIBUTING FACTORS: cock had not been wired in the open position. Wing tanks drained too low and on DATE steep turn air was sucked in by the engine driven fuel pump and as the a/c