D/A	DISON CE NECT OF THE PILOT	AIRFRAME FAILURE				ENGINE FAILURE						
PE OF	UNIT #5 E.F.T.S. COM.			PLACE M.A.				DATE 12.4.43 TIM 1055				1 1 / 6 /
λ	A/C TYPE Cornell I			10513			CRASH CAT. C.1	SE X ME		DAY X	NIGHT	MERTHER OR JUST
Ļ	NAME RA			NK No.	o. 1	DUTY	ULNI	RIES	IES		nous	
	R118584 LAC McLean, A.S.					PP	Nil			FATAL	YRULNI	S Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z
TYPE OF ENGIN										CARD SERIAL NO.		S SHOUTH OF THE SHOP
	TYPE A/I		No. EXTENT OF DAMAGE		RIAL No.	DATE	но	URS FLOWN BY P				1 1 2 6 7
	Corne						INST. NIGHT	ON TY		TOTAL DUAL SOL	LAST O 6 MOS.] <u>"</u> - /,&//
GORY	Rang	er 27287/4		1017								A O E CLOSE
ıω		NAL NO. & DATE UNIT NO. & DATE C		COM N	OM, No. & DATE REPOR			RT FILE DAT		DATE	/\$\/ [F	

DUTY ON WHICH ENGAGED: COURT OF INQUIRY, INVESTIGATING OFFICER Routine training. OR COMMANDING OFFICER'S REPORT: D-14 TM/ANT/PET NATURE OF ACCIDENT AND STAGE OF FLIGHT: A/C became stuck in soft ground while taxiing out to Control Tender. Strong tail wind. Was moving A/C with assistance of flight crewman. Engine running. Wind caught tail and blew A/C over on RECOMMENDATIONS: its nose. PRIMARY CAUSE: 35. Cross winds and gusts: ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER NiL. When A/C become stuck in soft ground, engine shall be stopped and A/C towed free by hand or by power, e.g. tractor. This will be embodied in Station Flying Orders as of this date. SECONDARY CAUSE OR CONTRIBUTING FACTORS: 1. Bad surface of serodrome. RECORDED BY DATE 36. Nosing up. CHECKED BY DATE R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41