

PURPOSE OF FLIGHT: TECHNICAL OFFICER'S REPORT: 104/116 / 11/11K Glide approach - steep turns - forced landing - precautionary landings. Ni 1 NATURE OF ACCIDENT: Witness states: Saw a/c S proceeding COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: E to W. A/C was about 2.000 in FINDINGS: SUMMARY No. height above water. Heard engine clear-CIRCUMSTANCES. A/C nosed down during a turn to ly and they appeared to be running in port while flying at an altitude of an estimated perfect order. A/C continued on in a 3,000' and dived vertically into the ground. straight line from E to W flving straight CAUSE. This accident was caused by the failure and level until it was over Dinner Point. of pilot to fly with sufficient accuracy while Then it turned to the left in a very flat executing a turn to port which resulted in the turn. Had just started to turn when the nose of his a/c dropping thus precipitating nose dropped and he continued to turn 90° him into a dive from which he was unable to re-) and by that time the nose was right down cover. and the a/c dived into the ground. CLASSIFICATION: RECOMMENDATIONS Ni 1 CONCLUSIONS OF AI.B. Diving turn to the left is a peculiarity of the Hampden. Pilot must correct the yaw by rudder first in recovery. This pilot probably was either not aware of the SECONDARY OR CONTRIBUTORY FACTORS: peculiarity or forgot it in emergency.

ACTION TAKEN: Nil R. C. A. F. L 20 (REVISED) 7M-4-43 (3202) K.P. 5051 H. Q. 885-L 20 C. C. LTD. 7084.43