

PURPOSE OF FLIGHT:	TECHNICAL OFFICER'S REPORT:	5
Routine training flights: NATURE OF ACCIDENT: Pilot and pupil returning from bombin training flight heard muffled bang as saw hole appear in stbd wing outboard of engine nacelle. Realizing stbd wir was on fire, pupil was ordered to abs	Cause obscure. IMPPED AA INCOURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: INCOURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: SUMMARY NO. 206C CONCLUSIONS: Fire in air caused by accumulation of great fuel or fuel fumes, either in exhaust tail pipe and on or area between fully lowered flaps and underside the of wing, ignited by cold engine "popping back", shortly after being re-statted. CONCLUSIONS OF A.I.B.: Agree. Although A.F.T.I. Loes not state that fuel cocks shall not be turned	() () ()
CLASSIFICATION: 18. Misc. Technical.	off to demonstrate single-engined flying the provision of that Instruction should hat have turned off fuel stop the engine.	icas tg
)) <u>SECONDARY OR CONTRIBUTORY FACTORS:</u>	· •)
28. Fire-In air.	ACTION TAKEN:	
)	ACTION TANCES.	.)