

))	DUTY ON WHICH ENGAGED: Forced landing practice. NATURE OF ACCIDENT AND STAGE OF FLIGHT:	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: Commanding Officers Report. DATE: 2-11-40))
)	In flight - struck high tension wires. Aircraft continued into field, cartwheeled from port to starboard wing, landed upside down at 180 Degree angle. PRIMARY CAUSE: In attempting to clear a Hydro line, engine failed to respond to throttle	Flight Lieutenant. (D.H.E. Drury.) RECOMMENDATIONS: That all pupils be instructed to place the carburetor manifold heat control in the "Hot Air" position before commencing forced landing practice.)
	lower part of undercarriage caught Hydro line. SECONDARY CAUSE OR CONTRIBUTING FACTORS: An error in judgment on the	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER)
	part of the pilot.	CHECKED BY DATE CHECKED BY DATE))