

DUTY ON WHICH ENGAGED:	OF INQUIRY, INVESTIGATING OFFICER
FLYING TRAINING.	MMANDING OFFICER'S REPORT:
	COURT OF INQUIRY
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	16-9-41
THE PILOT WAS FLYING AT A HEIGHT OF APPROX. 200	OSITION:
ABOUT 10 MILES FROM THE AERODROME. THE PILOT	SQUADRON LEADER G.M. MARTIN (C863)
ROCKED THE NC, THEN DID A ROLL TO THE RIGHT -	FLIGHT LIEUTENANT R. RENDLE (72209)
LOST ALTITUDE, LEVELLED - N OSED UP - STARTED	Pilot Officer A.J. Lewinston (83484)
ANOTHER ROLL WHICH WHEN HALF COMPLETED DEVLOP-	
ED INTO A SPIN. THE NC PARTLY RECOVERED AND W	NIL.
DOWN AT AN ANGLE OF 45 DEGREES APPROX. AND CRAS	The state of the s
PRIMARY CAUSE: THE ENGINE SPUTTERED AS IT BOCA	1200/A00/808/B/W
INVERTED IN THE ROLL.	,
1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	
LOW AEROBATICS RESULTING IN A SPIN.	NI TAVENI
	N TAKEN: DISCIPLINARY (B) TECHNICAL (C) OTHER
	DIBUTE THAT (D) FEOTING (C) OTHER
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
INEXPERIENCE ON THE PART OF PILOT, P/C MCLEOD.	RECORDED BY DATE
	CHECKED BY DATE