

Practising sequences 8-10-12-15	OR COMMANDING OFFICER'S REPORT:	
16-17-22. ATURE OF ACCIDENT AND STAGE OF FLIGHT:	R 170	
	DATE: COMPOSITION: 5 FC/ 1/2 / 1/2 / 1/2	
Metal airscrew tip blew off	<u> </u>	
causing excessive vibration necessitating a successful force	4	
landing.		
**********	RECOMMENDATIONS:	
	FEWER RIVETS IN THE AIRSCREW TIP WOULD LEAVE THE WOOD STRONGER	
RIMARY CAUSE:	AND SERVE THE SAME PURPOSE.	
livets pulled out on leading edge	•	
f metal airscrew tip allowing		
it to fly off.		
t to fly off.	ACTION TAKEN:	
t to fly off.	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
t to fly off.		
it to fly off.	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
it to fly off.	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
·	(A) Disciplinary (B) Technical (C) Other NIL	
ECONDARY CAUSE OR CONTRIBUTING FACTORS:	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER	-
econdary cause or contributing factors: Successful forced landing	(A) Disciplinary (B) Technical (C) Other NIL	-