

ĺ)	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER				
)	FORCED LANDING PRACTICE.	OR COMMANDING OFF			10-112-1128/4/	nd.
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: September	23rd,]	1941.)
)	MACHINE APPARENTLY WENT INTO SPIN AND HIT	COMPOSITION:	-	-•	•)
)	THE GROUND.	President		s/L	Maxwell, P.H.)
)		Member Member		F/0 F/0	Wurtele, D.B.	
)		RECOMMENDATIONS:		F/ U	Dibnah, R.H.)
))
	` `	PRIMARY CAUSE:		N.	Α.)
)	Insufficient air speed whilst doing a gliding turn causing a spin.					Ź
)	5 5)
)	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER					
)				Ni1		,
	,						1
	}	SECONDARY CAUSE OR CONTRIBUTING FACTORS:					
)	Aircraft spuninto ground.					
İ	;	- -				RECORDED BY DATE)
							_ ,
						CHECKED BY DATE	
	1)))))))))))