

Dual Instruction sequences l-lA-2-3-ly NATURE OF ACCIDENT AND STAGE OF FLIGHT: Aircraft appears to have hit ground at high speed and nosed in.	DATE: OCTOBER 30TH, 1941. COMPOSITION: President Sqn. Ldr. Member F.O. Member F.O. RECOMMENDATIONS:	White, R.J. (C.731) Kennedy, J.L. (C.1476) Coumans, O.B. C(5272)) ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ;
(I) All Instructors be fully qualified to recover from flat spins. (2) System as practised for signing out aircraft as serviceable at this school is questioned. Evidence submitted shows personnel not in possession of proper certificates. ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER N.A. (48 hour report D.6)			
SECONDARY CAUSE OR CONTRIBUTING FACTORS: Aircraft nosed into ground.		RECORDED BY DATE) ;