

DUTY ON WHICH ENGAGED: COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: Spinning instruction. Court of Enquiry. NATURE OF ACCIDENT AND STAGE OF FLIGHT: DATE:5-11-42 COMPOSITION: Aircraft was seen at about 500' Pres. S.L. A.C. Bailey making a gentle turn to the left -#31 EFTS De Winton, Alta. then spinning to the right. It Mem . S.L. R.F. Gladden # 3 EFTS High River. Alta. crashed. P.O. J.H. West # 5 EFTS High River, Alta. RECOMMENDATIONS: "It is recommended that the second explanation be considered and that instructions be issued to PRIMARY CAUSE: amplify the spinning pattern for incipient spins Pilot allowed aircraft to spin at and to make clear the correct method for preventlow altitude. ing the development of a spin from a badly executed turn. ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER NIL OBSERVATIONS. THE PILOT HAD A GOOD AMOUNT OF EXPERIENCE AND A GOOD REPUTATION. IT IS UNLIKELY THAT HE ATTEMPTED A SPIN TOO LOW. IT IS CONSIDERED THAT HE WAS ALLOWING THE STUDENT TO DO A FORCED LANDING PRACTICE AND THAT THE STUDENT WAS MAKING A LEFT HAND TURN WHEN THE AIRCRAFT STALLED TO SECONDARY CAUSE OR CONTRIBUTING FACTORS: THE LEFT, CORRECTIVE ACTION RESULTED IN A SPIN TO THE RIGHT - THE INSTRUCTOR PARTIALLY GOT CONTROL AND THE AIRCRAFT HIT AT Insufficient height to regain control steep ANGLE AND SLEWED SIDEWAYS. before striking ground." RECORDED BY DATE DATE