

)	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
)	STUDENT PRACTICING SPINS.	OR COMMANDING OFFICER'S REPORT:
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:
))	MOTOR STOPPED DURING SPIN AND AIRCRAFT WAS FOR LANDED IN DEEP SNOW, OVERTURNING.	CED POSITION:
)		RECOMMENDATIONS:
)	PRIMARY CAUSE:	
)	MOTOR STOPPED DURING SPIN.	
)		ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER INSTRUCTIONS ISSUED AS FOLLOWS:
)		THROTTLE IS LEFT OPEN SLIGHTLY, LEAVING AROUT 700 TO 1000 P. B.
)		INDICATED, THERE WOULD BE VERY LITTLE CHANCE OF THE ENGINE STOPPING PRIOR TO GR DURING THE SPIN. FURTHERMORE, WHEN PRACTISING SPINS FROM
)		A TURN WITH INSUFFICIENT POWER, IF THE ENGINE IS MERELY THROTTLED BACK TO APPROXIMATELY 800 R.P.M. INSTEAD OF CLOSING THE THROTTLE
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:	COMPLETELY, AND THE SPIN NOT HELD FOR MORE THAN IL OR 2 THERE
)	FORCED LANDING IN DEEP SNOW OVERTURNED	WOULD ALLEVIATE THE POSSIBILITY OF THE ENGINE STOPPING ON THIS TYPE OF SPIN, RECORDED BY DATE
)	AIRCRAFT.	DATE OF THE STATE
)		CHECKED BY DATE
}		