

1 o ct. so rodo	CHECKED BY DATE
Actual landing was made with wheels retracted.	RECORDED BY DATE
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
	Nil.
somewhat en the glide.	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
permitting the engines to load up	ACTION TAKEN:
pilot, in that he opened the throttles too quickly after	(ii('Winterization' of Cheetah Engines.
Inexperience on the part of the	conditions prevail.
PRIMARY CAUSE:	Intake will always be kept in "hot" except for "take off" whilst winter
)))	(i) A Local Order has been issued that the Air
	RECOMMENDATIONS:
	1400/200/00/01/01
to make forced landing.	Acting Flight Lieut. MILES, D.W.K.
Aircraft crashed whilst attempting	COMPOSITION:
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	INVESTIGATING OFFICER'S REPORT. DATE: 10th & 11th November, 1941.
Flying training.	OR COMMANDING OFFICER'S REPORT: