

DUTY ON WHICH ENGAGED: Training night.	OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Aircraft 5856 taxiing west on taxi strip after landing to taxi post,	CAN LA CA
when at intersection of tarmac fail to see aircraft 5857 also proceeding from tarmac to taxy post resulting in collision.	
PRIMARY CAUSE:	,
Pilets failed to see each other. (Note: these aircraft are not fitte with upper identification lights). Gallision	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER Recommended installing of upper identification lights.
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	y.
Collided with aircraft while taxiin	RECORDED BY DATE