

(()))))))))))))))))))))))))))))))))))
) DUTY ON WHICH ENGAGED: COURT OF INQUIRY, INVESTIGATING OFFICER)
) PRACTICE SINGLE ENGINE LANDING. OR COMMANDING OFFICER'S REPORT: N. 170	
) NATURE OF ACCIDENT AND STAGE OF FLIGHT: DATE:	
) INSTRUCTOR FAILED TO PLACE ALL SHITCHES IN THE COMPOSITION:	
) "ON" POSITION. WHEN OVERSHOOTING AND ATTEMPTING	
TO GO AROUND AGAIN THE LIVE ENGINE WAS INADVERTENTLY SWITCHED OFF. THE PILOT NOT REALIZING ALL SWITCHES IN	
THE "OFF" POSITION ATTEMPTED A CROSS-WIND LANDING RECOMMENDATIONS:)
THE TURN ACROSS WIND WAS INSUFFICIENT TO AVOID	3
COLLISION WITH BATTLE AIRCRAFT PARKED ON TARMAC.) PRIMARY CAUSE:	<i>)</i>
NIL)
CARELESSNESS ON PART OF THE INSTRUCTOR.)
)
ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER)
ENDORSATION OF P/O TROTT'S LOG BOOK IN ACCORDANCE WITH C.A.P.LOG)
AND PERSONAL ADMONITION.	
') <u>SECONDARY_CAUSE OR CONTRIBUTING</u> FACTORS:)
A SECONDARY CAUSE ON CONTRIBUTING FACTORS:)
) TURNED OFF SWITCHES ON LIVE ENGINE WHEN DEMONSTRATING RECORDED BY DATE	-
) A SINGLE ENGINE APPROACH AND LANDING. SIRCRAFT FORCED . (20))
) LANDER AND AND AND ANOTHER APPERAFT. To Enquire Trouble - achecked by DATE	. ,
(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	· ·
	, ,