

,	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	S Address of the second	)
ļ	Sequences.	OR COMMANDING OFFICER'S REPORT:		
1	NATURE OF ACCIDENT AND STAGE OF FLIGHT: Collision after landing-4709 swung after landing and collided with 4502 which had stopped airscrew on side of runway.	DATE: COMPOSITION:  COMPOSITION:  COMPOSITION:  COMPOSITION:	/ १ - १८५ भे	)
)	•	RECOMMENDATIONS:		
ŀ				5)
ļ	PRIMARY CAUSE:			)
)	Failure on part of pilot of A/C 4709 for not noticing stalled A/C 4502 and failure on part of his student for not warning pilot of stalled A/C in pathway.	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  (A) Trainees instructed to report all A/C near enough to cause an accident regardless of whether they deem it necessary.		)
secondary cause or contributing factors: 4502 failed to clear the runway.		Closer observation on particular control of the con	art of pilot.	)
ŀ	Partial ground loop for A/C 4709	RI	ECORDED BY DATE	
)	and also burst of throttle to prevent engine form stopping.			
)	R.C.A.F. FORM L20 REQ. 1247 10M—15-11-41	<u>ci</u>	HECKED BY DATE	)
)		) ) ) ) ) ) ) ) )	) ) ) ) ) ) )	)