

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
Scheduled Bombing Flight.	OR COMMANDING OFFICER'S REPORT: Investigating Officer's Rep
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Forced landing wheels up in open country.	DATE: 6-3-42 COMPOSITION:  F.O. E.O. Clark  No. 5 B & G School, Dafoe, S
PRIMARY CAUSE:	RECOMMENDATIONS:  That the new design of flame trap for Merlin engines which it is understood is now being manufactured be ambodied in place of the present type
Engine failure due bursteintakes:	which has proved to be unsatisfactory.
valves causing the flame traps to	1 M <sup>B</sup> -
17. Forced Landing	ACTION TAKEN:  ACTION TAKEN:  DISCIPLINARY (B) TECHNICAL (C) OTHER  Nil  Force landing following engine failure due to burnt inlet valves causing the flame traps to burn out.
SECONDARY CAUSE OR CONTRIBUTING FACTORS:  A/G landed in plowed field, with  slight damage.	TRECORDED BY DATE