

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	
Ferrying Aircraft.	OR COMMANDING OFFICER'S REPORT:	
NATURE OF ACCIDENT AND STAGE OF FLIGHT: A/C FLOWN BY FERRY PILOT ON TRANSFER FROM UNIT. THE PILOT TOOK OFF #3 RUNWAY TO THE SOUTH, MADE A LEFT CIRCUIT AND ON APPROACHING	DATE: COMPOSITION:	
NORTH END OF AERODROME MADE A STEEP BANK TO LAND WIT WHEELS RETRACTED. PILOT LANDED MACHINE PARALLEL TO #3 RUNWAY TO EAST OF IT.	RECOMMENDATIONS:	
Considerable damage was done to the A/C. PRIMARY CAUSE: Station Engineer States Radiator Shuzter	NII.	
BOTH OVER ENGINE FAILED.	ACTION TAKEN: (A) Disciplinary (B) Technical (C) Other	
17. Howeed Landing		
SECONDARY CAUSE OR CONTRIBUTING FACTORS: FORCED LANDING HITH WHEELS RETRACTED. To Engine Trauble - Cl	Recident RECORDED BY DATE	E
	CHECKED BY DATE	