

DUTY ON WHICH ENGAGED: Gunnery exercises. NATURE OF ACCIDENT AND STAGE OF FLIGHT: Engine failed on take off and pilot tried unsuccessfully to return aerodrome forced landing	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: Investigating Officer's Report. DATE: 12-3-42 COMPOSITION: Flt/Lt. Prendergast H.L. No. 2 B & G School, Mossbank.
with wheels retracted.	RECOMMENDATIONS: NIL.
PRIMARY CAUSE: Engine failure.	703
(15)	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
15 Hores Land.	Conclusions of A.I.P. Forced landing due to engine failure on take off.
SECONDARY CAUSE OR CONTRIBUTING FACTORS: Pilot unable to reach aerodrome	Cause of engine failure was the plugging and disintegration of the flame traps.
Lo Engine Trankle -	RECORDED BY DATE CHECKED BY DATE
))))))))))))))))))	CHECKED BY DATE