

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	
Practice landing.	OR COMMANDING OFFICER'S REPORT: R.170	
NATURE OF ACCIDENT AND STAGE OF FLIGHT:		
Pilot overshot on landing.	DATE: COMPOSITION:	
Touched down too far down runway, but could not get tail down probably	,	
because throttles were not fully closed.	RECOMMENDATIONS:	
010304.	RECOMMENDATIONS;	
PRIMARY CAUSE:		
A/C ran off runway into boggy groun	n.d.	
at and of minutes 1/0		
at end of runway. A C submerged to	•	
nacelles.	ACTION TAKEN:	
nacelles.	ACTION TAKEN: (A) Disciplinary (B) Technical (C) Other	
nacelles.	ACTION TAKEN:	
nacelles.	ACTION TAKEN: (A) Disciplinary (B) Technical (C) Other Interviewed and warned Log Book endorsed "Oyonahat	
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	ACTION TAKEN: (A) Disciplinary (B) Technical (C) Other Interviewed and warned Log Book endorsed "Overshot carelessness".	
secondary cause or contributing factors: A/G ran through fence on boundary of	ACTION TAKEN: (A) Disciplinary (B) Technical (C) Other Interviewed and warned Log Book endorsed "Overshot carelessness".	
1. Queraket	ACTION TAKEN: (A) Disciplinary (B) Technical (C) Other Interviewed and warned Log Book endorsed "Overshot carelessness".	-