

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
AS924 Solo night X6882 night dual.	OR COMMANDING OFFICER'S REPORT: R170
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: DEALFORM POSIXA
Pupil Solo in Oxford X6882 After having been given check dual at night attempted to take off along the taxying strip instead of the flupath and collided with another Oxford No. AR924 which was taxying towards him. The	
FLAREPATH, A DOUBLE LINE OF GOOSE NECKS FLARES WAS EXACTLY AS WHEN HE WAS HAVING DUAL. THE	RECOMMENDATIONS:
INSTRUCTOR IN THE SECOND MACHINE AVOIDED A HEAD ON COLLISION BY SWINGING HIS AIRCRAFT VIDLENTLY. PRIMARY CAUSE:	NII
S924 attempted takeoff on taxi	
	ng
trip instead of flare path collidi	
asg24 attempted takeoff on taxi strip instead of flare path collidi with X5882.	ACTION TAKEN:  (A) Disciplinary (B) Technical (C) Other
trip instead of flare path collidi	ACTION TAKEN:
strip instead of flare path collidivith X6882.  13. Collision  ECCONDARY CAUSE OR CONTRIBUTING FACTORS:	ACTION TAKEN:  (A) Disciplinary (B) Technical (C) Other  Disciplinary action is being taken. Pupil suspended from flying and log book endorsed.
strip instead of flare path collidivith X6882.  13. Collision  ECONDARY CAUSE OR CONTRIBUTING FACTORS:  Solo pupil collided with an aircra	ACTION TAKEN:  (A) DISCIPLINARY (S) TECHNICAL (C) OTHER  Disciplinary action is being taken. Pupil suspended from flying and log book endorsed.
strip instead of flare path collidivith 16882.  // B. Collisson  ECONDARY CAUSE OR CONTRIBUTING FACTORS:  Splor pupil collided with an aircra in the taxying strip when attempti	ACTION TAKEN:  (A) DISCIPLINARY (S) TECHNICAL (C) OTHER  Disciplinary action is being taken. Pupil suspended from flying and log book endorsed.