

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	R170)
Sunnery Exercise.	OR COMMANDING OFFICER'S REPORT:)
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Pilot tried to lower wheels but port wheel remained in same positi	DATE: COMPOSITION: COMPOSITION:)
He resorted to his emergency hand pump with no effect. Pilot landed with lower undercarriage in "Up" position.	RECOMMENDATIONS:)
PRIMARY CAUSE:	Nil)
Port wheel would not lower althoug)
UJC FAILLURE	ACTION TAKEN: (A) Disciplinary (B) Technical (C) Oth No disciplinary action take of the necessity for close ing devices. Pilots also w that the mechanical crank s	n. Maintenance wa scrutiny of wheel arned of the possi	lower- bility
SECONDARY CAUSE OR CONTRIBUTING FACTORS: A/C landed on one wheel, ground	operate in the air and required lower wheels.		
looping causing damage to the airframe and airscrew.	RE	CORDED BY D	DATE)
R. C.A.J. SORMEZ ERTO, ET GOT-15-11-41	сн	ECKED BY D	DATE)