

ļ	·) ·) ·) ·) ·) ·) ·) ·) ·) ·)))))))))))))))))))))))))))))
	Cross country navigation flight to Carberry. NATURE OF ACCIDENT AND STAGE OF FLIGHT: LAC. Komesch started engine 6f A/C 5853 without chocks, throttle half open, A/C moved forward and made turn to left, collided with A/C 5937.	COURT OF INQUIRY, INVESTIGATING OFFICE OR COMMANDING OFFICER'S REPORT: R170 DATE: COMPOSITION: RCA	
,	3,5,1.	RECOMMENDATIONS:	
)		Nil	
)	PRIMARY CAUSE		
)	Negligance of pilot in failing to		Marie Company of the
)	see that a/c chocks were in position and that throatle was set before	<u>.</u>	~
`	starting. Failure of pilot to stop	ACTION TAKEN:	<i>,</i>
	a/c either by use of throttle.	(A) DISCIPLINARY (B) TECHNICAL (C) O	
,	switch or brakes.	Students Log Book endorsed	
)	COLLIS IONS	Student awarded 14 days three days forfeiture of p	
)	19/		र ाज र)
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:)
)	A/C taxled into a/c 5937 causing		<u> </u>
)	damage to both a/c.		RECORDED BY DATE
)	R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41		CHECKED BY DATE)
)			