

. , , , , , ,	_,,,,,,,,,,,	, , , , , , , , , , , , , ,	,
) DUTY ON WHICH ENGAGED:) Solo circuits and landings.	COURT OF INQUIRY, INVESTIGATING OFFICER S REPORT:	CER)
NATURE OF ACCIDENT AND STAGE OF FLIGHT: A/C found crashed near Holson. Seemed to have dived vertically into the ground with full engin No witnesses & A/C was missing 5½ hours before it was found. The state of fuel before take-) off gave about 3 hrs. endurance	COMPOSITION: SLW-T. Brooks No. 39 1e. F/L R.F. Hunter, No. 34 P/O E. Swaine No. 34 F/L R.M. Paterson No. 1	S.F.T.S. S.F.T.S. S.F.T.S. 5 S.F.T.S.	
) PRIMARY CAUSE:		,	٠
Descure. 1) 23. NOT KNOWN. 23	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) (Nil.	OTHER)	
)	Conclusions of A.I.B. Same as findings of Court	of Inquiry.	
SECONDARY CAUSE OR CONTRIBUTING FACTORS:			
)		RECORDED BY DATE	
) R.C.A.F. FURM L20 REQ. 1247 13M—15-11-41))))))))))	CHECKED BY DATE	