

Routine gunnery exercise. ATURE OF ACCIDENT AND STAGE OF FLIGHT: Forced: landing with wheels up, and flaps down and after skidding for 100 feet broke through a wire ence. Glycol vapor prevented the ilot from seeing and as a result that the throttled down and made the	DATE: COMPOSITION: RECOMMENDATIONS:	19/r./GL/	ufifice/#	
ence. Glycol vapor prevented the ilot from seeing and as a result e throttled down and made the	RECOMMENDATIONS:			
orced landing. RIMARY CAUSE:	Nil			
Engine overheated and glycol fumes come back on pilot.				
7 FORCED LANDING	ACTION TAKEN: (A) DISCIPLINARY (B) TECH	inical (C) Other		
econdary cause or contributing factors: orced landing with wheels up				
NGINE TROVELE - ACCIOENT		RECORDED	BY D	ATE
C.A.F. FORM L20 REQ. 1247 10M-15-11-41		CHECKED E	3Y D	ATE