

DUTY ON WHICH ENGAGED: Solo practice flight.	COURT OF INQUIRY, INVESTIGATING OFFICE OR COMMANDING OFFICER'S REPORT:	<u>R</u>	<u>R170</u>)
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Coming in to land, another A/C	DATE: LM//33)
taxied on landing path and in attempting to change direction)
pilot applied coarse rudder and slight brakes causing A/C to ground loop.	RECOMMENDATIONS:)
-	Nil)
Harsh application of control. Failed to realize that another aircraft was obstructing his landing path. SECONDARY CAUSE OR CONTRIBUTING FACTORS:	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OT Nil	HER)
Aircraft ground looped.	Ī	RECORDED BY	DATE)
D C A T FORM 120 DEC 1247 101-15 11 41	-	CHECKED BY	DATE	j
R.C.A.F. FORM L20 REO. 1247 10M—15-11-41))))	$O \rightarrow O \rightarrow O$)