

Solo night flying prac		Y, INVESTIGATING OFFICER OFFICER'S REPORT:	
NATURE OF ACCIDENT AND STAGE (		20/100/POM	
pressure was low, inten	ided to land	7	
as near No.1 flare as p in so doing undershot, s			
fence causing it to nose	forward and RECOMMENDATIO	NS:	
finally turn over.  PRIMARY CAUSE:			
below the minium require	ed in Station		
Standing Orders.  3 Sudushot	ACTION TAKEN:  (A) DISCIPLINA  Disciplina	RY (B) TECHNICAL (C) OTHER Ary action taken - log book ende edience." has been made.	orsement
Standing Orders.	ACTION TAKEN:  (A) DISCIPLINA  Disciplina	ary action taken - log book endedience." has been made.	orsement
Standing Orders.	ACTION TAKEN:  (A) DISCIPLINA  Discipling  of "Dosobe  14 days C	ary action taken - log book endedience." has been made.	orsement
Standing Orders.  3 Ludushot  SECONDARY CAUSE OR CONTRIBUTI  Aircraft struck a wire causing it to nose forw turn over.	ACTION TAKEN:  (A) DISCIPLINA  Discipling  of "Dosobe  14 days C	ary action taken - log book endedience." has been made.	orsement
Standing Orders.  3 Sudushot  SECONDARY CAUSE OR CONTRIBUTION  Aircraft struck a wire causing it to nose forw	ACTION TAKEN:  (A) DISCIPLINA  Discipling  of "Dosobe  14 days C	ary action taken - log book endedience." has been madeB.	