

)		<b>,,,,,,,,,,,,,,,,</b> ,,,,,,,,,,,,,,,,,,,,
) )	DUTY ON WHICH ENGAGED: Familiarization flight on type.	COURT OF INQUIRY, INVESTIGATING OFFICER  OR COMMANDING OFFICER'S REPORT:
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: R.170
)	Ground looped on landing, engine stopped and caught fire on restarting. To avoid complete	COMPOSITION:
)	starting. To avoid complete cut-off pilot opened the throttle loading exhaust stack with raw gasoline, which caused the fire.	RECOMMENDATIONS:
)	PRIMARY CAUSE:	
) )-	Misuse of throttle.	) )
) )	2. Surry.	ACTION TAKEN:
)	2	(C) Lecture given to pilots on proper handling of Mercury engine. Pilot given flight check and report on his ability being forwarded.
ì	SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
)	3) Tir On Shound	RECORDED BY DATE
ا <b>ر</b>	20. Sec. 1247 10M-15-11-41	CHECKED BY DATE
)		