

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
) Sequences 10 15 16 22.	OR COMMANDING OFFICER'S REPORT:
nature of accident and stage of flight: Engine stalled in spin, forced landing attempted and field over- shot, struck ground and turned	DATE: 24-8-42. COMPOSITION: F/O Edwards, R.G. No. 7 E.F.T.S., Windsor, Ontario.
over.	RECOMMENDATIONS:
)	Attention of S.E.A.O. at No. 1 Training Command and advising #12 Technical Detachment for investigation
) PRIMARY CAUSE:	and reports.
Engine stopped while pupil pilet was carring out aerobatics due)
to carburettion. 17. Soverd Cayoung	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER NiL. CONCLUSIONS OF A.I.B. Pupil pilot force landed due to engine failure caused by improper setting by the manufacturers of the float level in the carburettor. On force landing pilot over
) SECONDARY CAUSE OR CONTRIBUTING FACTORS:	shot field stalled and crashed.
ground and turned over. 26. Engine Guille Con	RECORDED BY DATE
R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41	CHECKED BY DATE
)