

Night flying training.	OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Pilot taxied into trench filled	R.170 DATE: COMPOSITION: TBG/107/XG >
with soft earth, A/C tipped on nose.	RECOMMENDATIONS:
PRIMARY CAUSE:	·
Trench not properly filled by contractors workman. Aircraft deviated off runway when taxing and one wheel ran into	ACTION TAKEN:
trench. // Others	(C) Contractors were requested to notify any hazards left on the aerodrome.
<i>[]</i>	
SECONDARY CAUSE OR CONTRIBUTING FACTORS: Aircraft tipped on its nose.	RECORDED BY DATE
	RECORDED BY DATE CHECKED BY DATE