	101 218 10 15 15 15 15 15 15 15 15 15 15 15 15 15	CON EUSE VALLE	OR WOOLD OR WOOLD	11 1 15 00 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2. 240. 240.	ARS ENG MISE	
U PILOT OTHERS	AIRFRAME	FAILURE		ENG		LURE	
126 Squadron .	CAUSES O		DENTS	ļ	<b>L1-42</b> time L300 <b>-</b> BW&	77.6 7	
A/C TYPE Hurricane	No. BW676	CRASI CAT.	A	SE ME		NIGHT O	
NAME	RANK No.	DUTY	וטנמו	RIES	SEF	RIOUS > "	
Fawcett, G.H.	SGT R91963	SP F	illed.		FATAL	א א א א א א א א א א א א	
<u>и</u>					1	m 2	
Z 0 Z U						ARD GAL NO.	
и О							
TYPE A/F NO. EXTEN OF DAMA	T REPORT SERIAL	DATE HOURS FLOW!					
Hurricane SW676 Totall	у		NST. NIGHT -	ON TYPE	DUAL SOL	'	
Merlin 34269/214357 Tot	ally			İ			
0 0						1	
SIGNAL NO. & DATE UNIT NO.	& DATE COM.	No & DATE	REPOR	T F	ILE	DATE	
A 12   10-11							
NATURE OF ACCIDENT							

	<b>,,,,,,,,,,,,,</b> ,,,,,,,,,,,,,,,,,,,,,,,						
DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER						
Section formation cloud flying.	OR COMMANDING OFFICER'S REPORT:						
NATURE OF ACCIDENT AND STAGE OF FLIGHT: On take-off aircraft reached approximately 300 feet when blue and white smoke came from aircraft.	-/ / / / / / / / /						
Aircraft did sliding half turn to	000/2 1/ W/OV						
left and entered water, nose and	RECOMMENDATIONS:						
left wing striking first.	NiL.						
	CONCLUSIONS OF A.I.B.						
PRIMARY CAUSE:	Concur in the report. A further investigation is beiry						
lause is obscure, although	held to enquire fully into the reasons for finding						
exist that engine failure was	water in the refuelling tender and other A/C at Dart-						
at least the primary cause.	mouth.  ACTION TAKEN:						
2 .	Ni Disciplinary (B) Technical (C) Other						
14 OUT OF CONTROLLH	)						
	<i>)</i>						
SECONDARY CAUSE OR CONTRIBUTING FACTORS:							
Pilct lost flying speed in the turn	r						
and fell into a spin.	RECORDED BY DATE						
and fell into a spin.  26. Linging TROVERS - Accident	CHECKED BY DATE						
ACCIDENT	CHECKED BY DATE )						