737	40/ 80/	28 27 26 21 26 27 26 21 26 27 26 27	/ / /	22 21 5 JA 65 5 JA 65		8 17 R 15 OR 15	TEN ENGLE	MOUNT.	12 11 Ringer	300	9 6	20.	6 5	OLICE JACO LARGE
\overline{\gamma\circ}	i - i - i - i - i - i - i - i - i - i -				AIRFRAME FAILURE					ENG				
PE OF A	UN135 E	UNIBS E.F.T.S. COM. Neepawa, Man. 2				PLACE 2 miles Nort mile East of Ede				DATE 18-11-42 TH H.Q. FILE 1100-42			15 <b>45</b> 2	M. W.
1	A/C TYPE			No			CRASH CAT.		SE	ME		ΑY	NIGHT	o Web
1		er Moth			1,21,2			_C				x	<u> </u>	10101/37/
ᅪ		NAME		RANK NO. DUT				RIES			SERIOUS FATAL INJURY		ORTORIO	
	Wanlin, A. Hall, G.V.				/0 112325 AC. 132429		Ni Ni					. , , , , ,	INJORI	1.12 / 28/
E OF ENGINI									-			CA SERIA	RD AL No.	S JHO PRI
\ <u>{</u>	·					HC HC			URS FLOWN BY PILOTS			ots		1 1 / 6 /
		Tiger Moth 4242 Seri		REPOR FORM		DAT	- 1				,	TOTAL LAS		" PE OF
	Tiger						INS	T. NIGHT	DUAL	DUAL SOLO DUA				N T ARE OF
亻	G. Majo		Slight											<u> </u>
EGORY			ļ <u>-</u>										-	1-1 1/2/2
TEG	SIGNAL	SIGNAL NO. & DATE UNIT NO. &			ATE COM. NO.		DATE REPO		RT FILE		ILE	DATE		
/ ઇ	6 A-1101 19-11-42													
K	<u>' , , , , , , , , , , , , , , , , , , ,</u>	<del></del>	<del>, , , - , -</del>	7 /	TURE	O F		IDENT	7. 7	. /-	7. 7	<u></u>	/4 /	2/2/2
<b>~</b>	2 E V	9 4	6 01	11 (21	EI PI S	(6 / 5 1	Z1 B1	/ / /	15 55	EZ (1)	7 SZ	20 / 26	/2 / 2 / 2 / 2 / 2 / 2 / 2 / 2 / 2 / 2	62 06 18

		1							
DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER								
Dual instruction forced landing.	OR COMMANDING OFFICER'S REPORT:	3							
NATURE OF ACCIDENT AND STAGE OF FLIGHT:    INSTRUCTOR SMITCHED OFF PETROL COCK TO CHECK   PUPIL S COKCPIT DRILL. BUPIL FAILED TO NOTE   THIS AND INSTRUCTOR STATED THAT HE PUT PETROL   COCK BACK INTO THE "ON " POSITION. THE PETROL	DATE: COMPOSITION: ILFM PCDE/ES/PM/PH/IL								
COCK WAS OFF FOR ABOUT 15 SECONDS. WHEN THE PUPIL HAD COMPLETED THE ATTEMPT, INSTRUCTOR OPENED UP THE THROTTLE AND SHORTLY AFTER THE ENGINE FAILED AND HE ATTEMPTED TO LAND IN A SMALL OPENING IN SOME WOODS. ON LANDING THE UNDERCARRIAGE STRUCK SOME ROCKS, CAUSING IT TO COLLAPSE AND THE PROBELLOR AND LOWER MAIN PLANE STRUCK THE GROUND. DURING THE GLIDE THE PILOT STATED THE ENGINE WAS WARMED BY OPENING THE PRIMARY CAUSE: THROTTLE SEVERAL TIMES.	RECOMMENDATIONS:  AN ORDER IS BEING PLACED IN PILOTS ORDER BOOK STATING THAT SWITCHING OFF THE PETROL COCK IN FLIGHT 18 FORBIDDEN.	-							
ENGINE FAILURE.		ļ							
17. FORCED LANDING	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  NIL.	`							
)	1								
PILOT IN ATTEMPTING TO FORCE LAND, LANDED ON ROCKY GROUND WHICH CAUSED THE UNDERGARRIAGE TO COLLAPSES 26 ENGINE TROJELE -	RECORDED BY DATE								
) R.C.A.P. FORM L20 REQ. 1247 10M—15-11-41	CHECKED BY DATE								
<u>, , , , , , , , , , , , , , , , , , , </u>									