

	Control (Control)
DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
Dual instruction.	
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Engine started to run rough and sputter at 400 feet. Instructor took over control. As engine cut out instructor turned the gas and switch off and closed the throttle.	DATE: OFM ET/NK/NK/O. COMPOSITION: RECOMMENDATIONS:
Forced landed in tree area. PRIMARY CAUSE:	More care in running up engines prior to take-off.
Engine failure. Possibly due to cold engine.	
17. FORCED LANDING	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER Nil.
SECONDARY CAUSE OR CONTRIBUTING FACTORS: Engine Fan rough causing a/o to	
A/G forced landed in trees.	26. ENGINE TROUBLE -
R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41	ACCASENT CHECKED BY DATE