A/C	PILOT OTHERS			RFRAME	FAIL					NE FAIL	LURE	West of Street
PE OF ,	UNIT No.36 S.F.T.S Penhold, Alta.			ACE		il R.I.		DATE H.Q. F	5-1-4	43 TIME	1640	1 1
۲	A/C TYPE Oxford		No	. X7122		CRASH CAT.	С	SE	ME	X DAY	NIGHT	
	NAME	R/	ANK	No.	DUTY		INJU	RIES		SEF	งเอบร	
Ш Z	Jackson, F.H	[., I	AC	1389598	PP	Nil	1			FATAL	YAULAI	1:14 / 28/
PE OF ENGINE										ARD NO.	S O O O O O O O O O O O O O O O O O O O	
ĭ	TYPE A/F	EXTENT	REPO	ORT SERIAL	DAT	_	но	JRS FLOWN BY P		Y PILOTS		
	& ENGINE No. Oxford X7122	OF DAMAGE Slight	FOF	RM No.		11	NIGHT	ON T		TOTAL DUAL SOL	LAST 6 MOS	
RY		577 & A2258	340	Nil								
EGO												

)	, , , , , , , , , , , , , , , , , , ,	· ·
()	DUTY ON WHICH ENGAGED: . COURT OF INQUIRY, INVESTIGATING OFFICER)
١,	Precautionary Landing Practice. OR COMMANDING OFFICER'S REPORT:	Ś
	D.14	, .
,	NATURE OF ACCIDENT AND STAGE OF FLIGHT: DATE:	
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT: On throttling back at end of runway COMPOSITION: A/C sand and bounced. An attempt to)
))
)	correct this by use of throttles was	,
	made but A/C again bounced heavily and stalled at about 3 to 4 ft. and RECOMMENDATIONS:	,
	port wing dropped and wing-tip)
	scraped along ground.)
)	PRIMARY CAUSE:	
)	58. Precautionary landings.)
\leftarrow)
)	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER	Ó
)	Ni 1	,
	Pupils ability being checked to determine	- 1
,	advisability of continuing his training.)
))
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:)
)	Port wing tip struck ground due)
ì	to insufficient corrective action recorded by date to prevent stall at 3-4 feet.	
)	R.C.A.F. FORM L20 REQ. 1247 10M—15-11-41 CHECKED BY DATE)
1)