

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
Night flying. Circuits and landing	OR COMMANDING OFFICER'S REPORT:  Del4
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: COMPOSITION:  LUC / PCDUF / UCD L
A ircraft landed with undercarriage retracted, after pilot failed to carry out drill of vital actions on down-wind leg and forgot to lower u/C and landed on flare path.	RECOMMENDATIONS:
PRIMARY CAUSE:  34. Wheels up landing.	
17 Margel Land	ACTION TAKEN:  (A) Disciplinary (B) Technical (C) Other  (A) Log Book endorsed "Gross Carelessness".  Awarded 14 days C.C., and transfer to next Course.
SECONDARY CAUSE OR CONTRIBUTING FACTORS: Carolessness on part of pilot.	
32 W/6 Drill - m'alin	RECORDED BY DATE
The state of the s	CHECKED BY DATE