o	OSO NO		LRERAME		ALSKE NEW OF THE OFF	ENGINE		
Ā			SES O		CCIDENTS		11	1 / 12/0
Ö	UNIT 32 0.T.U. COM.				200 yards	H.Q. FILE 1300	1735	1 1 / .6
YPE	Patricia Bay, B.C. W.A.C		S.W. of	No.	2 Runway.	SE ME	D-ANILO DAY NIGHT	
	TYPE Hampden I		ANLL	١	CAT.	" x	x	10101/62
	NAME	RANK		DUTY	INJUF		SERIOUS	DE OF
	Thomas, J.H.	SGT	1434959	P	Nil		FATAL INJURY	
	Ankerson, J.E.	SGT	1318208		Nil			E Z THER
Z	Kasakewigh, A.	SGI	R86752	WAG	Nil		CARD	1 12 / 32
EZ O							SERIAL NO.	S OF S
9							$c \mapsto N$	
ЫE				<u></u>			<u> </u>	
<u></u>	TYPE A/F No. EXTENT & ENGINE No. OF DAMAG		PORT SERIAL	DAT	E HOU	ON TYPE		N CHU
	Hampden I ANLIO Total				INST. NIGHT		TOTAL LAST	[] \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
_	Total							0 H 47/04
λH	Pegasus XVIII P239931 &	S186	239 Sari	ous				111~1/ベビ
EGO				<u> </u>				
-	SIGNAL NO. & DATE UNIT NO. &	DATE	сом.	. No. & I	DATE REPOR	T FILE	DATE	IJK♡

DUTY ON WHICH ENGAGED: COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: Low flying over sea. COURT OF INQUIRY NATURE OF ACCIDENT AND STAGE OF FLIGHT: DATE: 26 Jan./43 S/L. N, K. Loyd, ##32 0.T. U. Pilot undershot aerodrome when COMPOSITION: F/L. W.E. Shaw, #32 O.T. U. attempting to land on one engine. /F/O. J.S.Dobson, #32 O.T.U. Port engine cut out near James Island and pilot could not make RECOMMENDATIONS engine give power. That all pupil pilots be impressed with necessity for carrying out single engine flying practice whenever possible. PRIMARY CAUSE: CONCLUSIONS OF A.I.B. 54. Engine failure in the air. What might have been a successful forced landing "That accident was due in 1st instance was undoubtedly marred by inexperience of pilot. to partial failure of port engine TAXXIONXINGEN: However the port engine failure might have) 2ndly to inexperience of vilot in single engine flying on this type it to become too cold. NOTE: No mention is made of the dew point at the time of accident or the possibility of icing. no mention made of the reason for the port oil SECONDARY CAUSE OR CONTRIBUTING FACTORS: tank holding only 1 gellon. Possibly cold weather. RECORDED BY 25. Inexperionce DATE 42. Fire after landing with A/C extinguisher) DATE