

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
Flying training.	OR COMMANDING OFFICER'S REPORT: D-14
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: OFM A DICCIONAL
Engine failed at 200 feet after	COMPOSITION: OF PURIOR ESINK/NK/D
take-off. Aircraft forced landed and turned over in snow.	
	RECOMM ENDATIONS:
	More care on the part of the pupil to ensure that
PRIMARY CAUSE:	the engine was fully warm before take-off, and in opening the throttle slowly.
13. Engine failure.	•
15 Jones Land.	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER NiL.
,	
/-	
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
It is possible that the engine was	A RECORDED BY DATE
slightly cold, and that the student opened the throttle too quickly.	C NECONDED BY DATE
	CHECKED BY DATE
Tidescitie	