	1050 / Ket / Ket		201 10 1 10 10 10 10 10 10 10 10 10 10 10					1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		COL GHI		LURE	47
A/C	O PILOT OTHERS AIRFRAME FAILURE ENGINE FAILURE CAUSES OF ACCIDENTS												
EOF	UNIT 5 BR	PLACE				-	DATE 7-1-43 T C655				/ 65		
٦ ک	Gander,	NELD.	E.A.C	No.	ander		CRASH		SE	ME	100-91 DAY	NIGHT	1 12 1/8/
	TYPE			1	ากวก		CAT.	\mathbf{A}					10101/32
	Cango A			RANK NO. DUTY			1	INJUI	RIES			SERIOUS >	
				S/L C	1270	D	Missin	e V	illed	33 od		INJURY	A U S I
Э	Small, N.E. Tingle, A.M.				J5767 2P Hissins			_	Killed		5	2	" Z /x [©] /
GINE	Hudson, D.L.			F/S F	R92324 Nav Hissing Killed CARD						1 121/s^>		
ENG	Mang	an, J.T.		F/S F	169117	TAG	Missin	g K	illed			IAL No.	S OF WE
P	Bann	ing, J.E.	.V.	F/S F	69377	MAG	Missin	l g					
PE (Mhite, H.E.			SGT B84515. Eng			Higging K		illed			4	
7	TVDE A/E			CERCET SERVICE				но	URS FLOWN BY FILOTS				
	& ENGINE			FORM	No.	DAT		NIGHT	ON T	YPE	TOTAL	LAST	STA TAKE
	Canso A	9737	Total	<u> </u>	1 1				DUAL	SOLO D	UAL SOL	_O 6 MOS.	
<u>-</u>	Wasp	9737 7853/419		r i ous									0 m 47/0 4
ORY		9714/119	ხ0 <u>⊥5 Se</u>	r i ous						-			1-1 /25
EG													
CAT	SIGNAL NO		UNIT No. &	DATE	сом.	No. & E	DATE	REPOR	*1	FILE		DATE	11 N
CA	X 133 A	27 8-1	UNIT NO. &	DATE	COM.	140. & L	7.1.2	. KEI OI				57.12	

, , , , , , , , , , , , , , ,	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,							
DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER							
Anti submarine sweep.	OR COMMANDING OFFICER'S REPORT:							
NATURE OF ACCIDENT AND STAGE OF FLIGHT: A/C heavily loaded and throttle back 30" boost probably caught in severe down draft before	COURT OF INQUIRY S.L. Volk, S., R.C.A.F. Station Torbay S/L. Mulvihill, No. 1 Group S/L. Gilchrist, No. 1 Group							
reaching sufficient height after take off to avoid colliding with	RECOMMENDATIONS:							
ground.	(A) A PILOT, BEFORE MAKING A NIGHT FLIGHT ON HEAVY A/C (WHICH HE HAS NOT FLOWN FOR SEVERAL MONTHS), SHOULD BE COMPELLED TO MAKE A FAMILIAR-IZATION FLIGHT IN DAYLIGHT.							
Severe down draft in heavily leaded condition at moment	were down draft in heavily (B) THAT WHERE POSSIBLE, PILOTS UNFAMILIAR OR NOT RECENTLY ACQUAINTE WITH THE LOCAL TOPOGRAPHY OF AN AIRPORT, MAKE A FAMILIARITY FLIG							
of commencing turn on to								
14 Out of Contral	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER NIL. CONCLUSIONS OF A.I.B. AGREE WITH THE FINDINGS AND WITH THE REMARKS OF THE A.C.C. No. 1 GROUP. WHILE AGREEING WITH THE FINDINGS IT IS CONSIDERED THAT A CONTRIBUTORY CAUSE WAS THAT THE PILOT THROTTLED BACK TO 30 INCHES OF BOOST BEFORE HE REACHED SUFFICIENT ALTITUDE ESPECIALLY IN VIEW OF THE LOAD HE CARRIED							
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	AND THE TURBULENT AIR CONDITIONS SOUTH WEST OF THE AIRPORT.							
Inexperience on type at night. Faulty setting of altimeter.	RECORDED BY DATE							
R.C.A.P. FORM L20 REQ. 1247 10M15-11-41	CHECKED BY DATE							