

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	)
Warming up engine at night.	OR COMMANDING OFFICER'S REPORT: D-14	- 1
NATURE OF ACCIDENT AND STAGE OF FLIC	SHT: DATE: TO PART	
While taxiing A/C into hanga	r, when COMPOSITION:	)
told to stop pupil did so but		``
slipped forward on the inclin		,
into hangar door breaking pro	-	)
blade.	RECOMMENDATIONS:	
		)
PRIMARY CAUSE:		· · · · · · · · · · · · · · · · · · ·
R. Hitting obstruction.		)
2. Hitting obstruction.		
7		)
	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER	)
	Log book endorsed "Carelessness" and logged.	,
,		)
		)
	•	)
SECONDARY CAUSE OR CONTRIBUTING FACT	TORS:	,
Carelessness on part of pile		,
taxiing too close to hangar	on RECORDED BY DAT	re )
slippery surface.		
	CHECKED BY DAT	TE )
) ) ) ) <b>) ) ) ) ) ) )</b>		, , ,
		1 1 1