

DUTY ON WHICH ENGAGED: Wireless training exercise.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:	,
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Engine dropped 500 rev's. Pilot switched tanks, applied pressure by wobble pump without improvement. Enguted normal forced landing.		
PRIMARY CAUSE:  54. Engine failure in the air.  Dirt on needle valve seat in carburettor prevented needle valve from closing.	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER	) ) )
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	RECORDED BY DATE	- -
	CUCCVED BY DATE	-