

DUTY ON WHICH ENGAGED: Section attacks.	COURT OF INQUIRY, INVESTIGATING OFFICER'S REPORT:	.	
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Engine failure on take off. Pilot throttled back, attempted to land a he was overshooting runway, retract u/c and landed on belly off end of runway.		PESINAMA	loops
PRIMARY CAUSE: 13. Engine failure. Runway wet in spots from melting snow. Possible water thrown up into carburettor. 15. Faccal Land.	ng <u>ACTION TAKEN:</u> (A) Disciplinary (B) Technical (C)	OTHER	
SECONDARY CAUSE OR CONTRIBUTING FACTORS:			
26. Engur trouble-accide	al	RECORDED BY	DATE
R.C.A.F. FORM LZA REQ. 1247 10M-15-11-41		CHECKED BY	DATE
() () () () () () () () () ()))))))))))))))))))