

DUTY ON WHICH ENGAGED: COURT OF INQUIRY, INVESTIGATING OFFICER Submarine spotting exercise. OR COMMANDING OFFICER'S REPORT: COURT OF INDUIRY S/L. Wilson, J.T. (C244) NATURE OF ACCIDENT AND STAGE OF FLIGHT: DATE: 24 March/4 Pilot flying No. 3 in formation F/L. Austin, E.R. (C1582) COMPOSITION: (F/O. Hay, R.D. (J7608) line astern crashed into tail of No. 2 directly in front, severely damaging his propellor. He managed to land at base. 5420 went out of RECOMMENDATIONS control and pilot bailed out into See Summary No. 886 for recommendations re sea the water. Body was recovered four rescues. hours later. PRIMARY CAUSE: 26. Collision in the air. **ACTION TAKEN:** (A) DISCIPLINARY (B) TECHNICAL (C) OTHER CONCLUSIONS OF A. I.B. AGREE WITH FINDINGS. LACK OF PROPER UNDERSTANDING BETWEEN PILOTS AS TO TYPE OF LINE-ASTERM FORMATION TO BE CARRIED OUT. LACK OF UNDERSTANDING BETWEEN GROUP OPERATIONS, SECTION CONTROL. FLYING CONTROL AND STATION OPERATIONS AS TO SIGNALS AND MESSAGES ALSO LACK OF SEA RESCUE ORGANIZATION, INCLUDING POORLY PAINTED MAE WESTS, LACK OF DYES AND SIGNALLING DEVICES IN DINGHIES. SECONDARY CAUSE OR CONTRIBUTING FACTORS: THE MARINE CRAFT CREW FAILED TO KEEP A KEEN LOOKOUT. DID NOT SEE CRASH 32. PILOU ETTOY. SUDDEN THROTTE HAS BACK OF NOR SEE PILOT BAIL OUT ALTHO POSITION OF CRASH WAS IN VICINITY OF THE BOMBING RANGE WHERE MARINE CRAFT RECORDED BY DATE WAS ON DUTY. AND COLLIDER CHECKED BY DATE R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41