

		, , , , , , , , , , , , , , , , , , ,	, ,
	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	•
,)	OR COMMANDING OFFICER'S REPORT:	
,	NATURE OF ACCIDENT AND STAGE OF FLIGHT: A/C swung on landing, pilot was unable to check swing due to	DATE: LS/PSS/UBF DIA 6 M	
	partly defective port brake. Struck snow-bank and bent one blade of airscrew.	RECOMMENDATIONS:	
,)		
: .	PRIMARY CAUSE: 61. Swinging on landing.		
;	2. Luing.	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
		NiL.	
	SECONDARY CAUSE OR CONTRIBUTING FACTORS:		
	46. Brake failure.	RECORDED BY DATE	
	,	CHECKED BY DATE	
i	R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41	CHECKED BY DATE	