									\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		() (s) (o) (s) ENGI		FAIL		
Ϋ́ -	PILOT	OTHERS	C	AUS	ES O		URE	DΕ	NTS					0 1. 2	
PE OF	Oshawa, Ont.				No. 1 Runway, Aero				PATE 28-3-43 THE PROOF H.O. FILE 1100-42					1140 6	METHER WELLER
> F		er Moth	82¢	No.	4216		CRASH CAT.	C	12	SE .	x ME	D	X AY	NIGHT	10101/32/
╝	A.V. SALECCO SHIP CHARGE OF THE	NAME	R	ANK	No.	DUTY			NJU	RIES			SERI	ous	De Constitution
	O'Brien	, J.A.	I	AC	R170762	PP	1	Vi l				F	FATAL	INJURY	ELLANES OF THE
E Z													CA	- 12 THEE	11217.67
ZIOZU													SERIA		
PE OF														λ	11 1/3//
ĭ ⊢	TYPE A/F		EXTENT	REPO	RT SERIAL	DAT	_	н		URS FLOWN BY P			PILOTS		1 1 1/.57
	& ENGINE		EXTENT OF DAMAGE	FOR	RM No.	UAI	li .		NIGHT	ON T			TAL	LAST	171 1 / 4: /
4	T. Moth	4216	Slight	i						DUAL	solo	DUAL	' solo	6 MOS	- 0 m 47.64
ORY	G.Mjr.	7216	Nil												1*1 1/25/2
ATEG	SIGNAL No.	o DATE	UNIT No. & D	ATE	COM	No & E	DATE	T	REPO	3T	F	LE		ATE	TO STORE

	1)))))))	·))))))))))
ſ	1	DUTY ON WHICH ENGAGED: COURT	OF INQUIRY, IN	VESTIGAT	ING O	FEICE	R							
			OR COMMANDING OFFICER'S REPORT:											
	,					14.								
)) NATURE OF ACCIDENT AND STAGE OF FLIGHT: DATE:		,	/)
)	, Pupil coming in to land levelled COMPOS	SITION:				i.							
		off too high and bounced. He then												,
)	applied throttle, again levelling	r ·	* T)
	,	off, pulled control column back		¥	a.									
)	harshly and dropped A/C in heavily. RECOMM	MENDATIONS:	<i>LH</i> ,	100		فينكر							
				· 14/	11 0	11	A -F)
)	•		•)
)) PRIMARY CAUSE:)
)	39. Flattening out too soon.												1
	(H. Stany.												
,)	1 /1)
)	ACTION (A) D	TAKEN: ISCIPLINARY (B)	TECHNICAL	(C)	OTHER	,)
l	1	1		,		ΠL	21							ĺ
	′	<i>'</i>			•)
İ)))
	}))
	ı	SECONDARY CAUSE OR CONTRIBUTING FACTORS:												
	′									•				}
)	40. Heavy landing - flying into	.*			R	ECORDED	BY			D	ATE	. :)
))									-	-		
	ì	1				_							-	
	/	T.				С	HECKED	BA			D	ATE)
l	3)))))	1 1	ì	1 1	``	`))		λ.	X	`