

	, , , , , , , , , , , , , , , , , , ,)))))
DUTY ON WHICH ENGAGED: Night solo training flight.	COURT OF INQUIRY, INVESTIGATING OFFICER	
	OR COMMANDING OFFICER'S REPORT: D-14	
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:	
Pilot undershot on appraach and struck a telephone pole as he	COMPOSITION: 2 - COMPOSITION:	
opened up his throttles. Pupil	•	
landed with the U/C lights green and no horn blowing. Port U/C	DECOMPTIONS	
collapsed and the A/C swung to the	RECOMMENDATIONS:	
) left and the left wing grounded.	V.	,
PRIMARY CAUSE: 30. Undershooting runway.		
3. Madershot		
3	ACTION TAKEN:	·
	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER Log book endorsed.	
)		
) SECONDARY CAUSE OR CONTRIBUTING FACTORS.		
secondary cause or contributing factors: Hitting obstructions.		
34. Wheels up landing.	RECORDED BY	DATE
24. Carelessness	-	
1	CHECKED BY	DATE