1 -	ON LE LE LES LES LES LES LES LES LES LES L	Chiles his Si			FALL		Seti 140	RIMP FUE	ENGI		ENG PR		N. S.
	INST 45 5 6 6 6 800M RELACE 2 77 LAG MARTIN AT NO DURA'S 12 4 44 10060 1 1												
A/ TY	Macconald, Wang #2 10		No.	1909		CRASH CAT. <b>C</b>	SH C		SE ME		DAY		1 S 1 V
	NAME		RANK	No.	DUTY <b>P</b>		ענאו	RIES			SERIO		CAUSE
<u> </u> _	Bartlett, W.A.			PO J13344		Nil					ATAL		S A
ш	Bazlik, V.		R164370		Nil		ba:				1I 1		
Z N	Cummins, V.C.			AC R162693 AG Nil				D					
										_	- CITIZE	<del>[</del> ]	111
PE OF	·				-						1/	$\sqrt{}$	i   1
1≻[	TYPE A/F No. EXTENT OF DAMAG		REPORT SERIAL		DAT		HOURS FLOWN				BY PILOTS		
						- 1	NIGHT		TYPE		TAL	LAST 6 MOS.	STA FLI
Ш	Battle #1909	Slight	<u>;</u>	_				DUAL	SOLO	DUAL	SOLO	U MICOS	
7	Merlin V 119	267/4183	Nit.										0 m
		-											HULL
√ <u>ü</u> ⊨	SIGNAL NO. & DATE UNIT NO. &		DATE COM.		N - 0	NATE I	REPO		RT FI		D/	ATE.	

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER )								
Ounnery exercise.  NATURE OF ACCIDENT AND STAGE OF FLIGHT: Engine failed. A/C force landed with wheels up.	DATE: COMPOSITION:								
)	•								
;	RECOMMENDATIONS:								
PRIMARY CAUSE / Jaced Carry Garages  Gas filter completely Freen with	Disciplinary action taken against Motor Mechanics Motor Transport for neglect in failing to ensure that all water had been drained out of Refuelling Tender after same had been used for carrying water.								
) ice. Also jet wells, needles and fuel lines.	ACTION TAKEN								
	ACTION TAKEN:  (A) Disciplinary (B) Technical (C) Other								
being in its fuel system which result in ice having formed & increased in	lted  bulk  CONCLUSIONS OF A.1.B. (912)  Agree with findings. See								
, until the fuel lines, filter & carbo	ettor summary for details.								
hecame plugged with ice which cut of SECONDARY CAUSE OR CONTRIBUTING FACTORS:	ff supply of fuel.								
, 26. tengur traubh 26	RECORDED BY DATE								
) R.C.A.F. FORM L20 REQ. 1247 10M—15-11-41	CHECKED BY DATE								