32 3	// / /	/		22 21		17	15 15 14 13 1	2 41 10 9	B 7	6 5	4 3 2 1
- N			28 4 62 41					ENGII			
4 1 5	PILOT OTHERS AIRFRAME FAILURE ENGINE FAILURE CAUSES OF ACCIDENTS										
S S S S S S S S S S S S S S S S S S S	UNIT #5 E.F.T.S. COM. High River #4 TC			li	M.A.			DATE 24.4.4 TIME 0214 H.Q. FILE 1100-105-19			M 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
TYPE TYPE	A/C TYPE Corn				°. 1051	9	crash cat. C.10	SE ME	DAY	NIGHT X	10101/32/ /
	NAME RAN			RANK	No.	DUTY	AUCNI	R∣ES	SERIO		A E DRY JAT
(a a /	Twiss	, R.D.		FS	R97943	FI	Nil_		FATAL		S P P P P P P P P P P P P P P P P P P P
(6 / 1	Erskine, W.S. LA			LAC	R171895	PP	Nil			- 1	しばしゃン ノニ
2 A Z D Z									CAI SERIA		S O O O O O O O O O O O O O O O O O O O
12 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1								- 1		
E	TVDE A/E EYTENT			REI	METOKI DATE IL						
7	& ENGINE	No.	OF DAMAG		ORM No.		INST. NIGHT	ON TYPE	TOTAL	LAST 6 MOS.	STA AREOTE
7	Cornel			idus	!			DUAL SOLO	DUAL SOLO	0 3.03	15101/ <i>8</i> 6/ /
- 1 2 ≥ E	Ranger	27045/28	84 Ni	٠ـــــــــــــــــــــــــــــــــــــ							
9 / 19											T O STATE A
\$ \\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	SIGNAL NO. & DATE UNIT NO. & DAT				TE COM, No. & DATE REPO			ORT FILE DATE		ATE	
0	T.87 2	4.4.43									1 12 12 300 N
كر*	NATURE OF ACCIDENT										
	2 8 7 9	9 4 8	6 01	11 /21	EI VI S	~/	71 81 61 02 1	12 22 E2 P2	26 25 SE	/2 BS	62 06 18 28

)	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICERS PERCENT.						
}	Routine night flying circuit practi	CE OR COMMANDING OFFICER'S REPORT:						
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:						
)	Undershot on approach, struck a	DATE: COMPOSITION: LU/FSU' -						
)	fence and ended up in bushes on							
()	north end of field.							
)		RECOMMENDATIONS:						
)		More caution to be exercised on part of instructors in future in night dual. Had the occupants been injured, their resume would have been dangerously impeded by the lack of two-way radio communication between tower and tender. This equipment is absolutely vital in night flying exercises.						
)) \	30. Undershooting runway. 3. Undershooting runway.							
,	4 2-1	ACTION TAKEN:						
)		(A) DISCIPLINARY (B) TECHNICAL (C) OTHER						
)		Instructors log book endorsed.						
)		ì						
)	ا جو المنظوم ا المنظوم المنظوم المنظو)·						
)	SECONDARY CAUSE OF CONTRIBUTING FACTORS:	ϵ						
)	41. Hitting obstructions.	RECORDED BY DATE						
)	24. Carelessness.	ACCORDED DI DATE						
ì	R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41	CHECKED BY DATE						
,								