)/C	PILOT OTHERS	AIRFRAME FAILURE						ENGINE FAILURE				
TYPE OF A	#133 Squadron WAC	PLACE OF ACCIDENTS In Flight east of Langley Prairie										1,457
ΤY	A/C TYPE Hurricane 11B		No. 5381			CAT. D.1 1/2		SE ME		DAY NIGHT		10101/3
_	NAME	RAN	K No. DUTY		DUTY	ı	NJUR	IES		SERIC	ous >	ELLAI AUSE
PE OF ENGINE	Gaskin, R.A.	F	S R	109667	P	Nil				CAR		S S S S S S S S S S S S S S S S S S S
7	TYPE A/F NO EXTENT	R	EPORT	SERIAL	DAT	_	нои	URS FLOWN BY PILOTS				1/6
	RENGINE NO. OF DAMAGE HUrricane IB #5381	Sli	ght	No.	DAT	INST.	NIGHT	ON TYPE	DUAL	SOLO	LAST 6 MOS.	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -
ORY	P.Merlin 41-48082/A468	5										G H (V)
E G		DAT			No. & [		REPOR		ILE		ATE	

Dog fighting practice.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT:  A/C on recovery from spin pulled out from resultant dive low over  a road striking wires strung along road.	DATE: 12 April/43 S/L. W.C.McDowell, #3 R.D. COMPOSITION: F/O. B. Moore, WAC.
PRIMARY CAUSE:  23. Spinning.  22. Collisións Obstructions  22	RECOMMENDATIONS:  It appears desirable that some definite record be maintained of before-flight, between-flight and after) flight inspections to ensure that such inspections are made on all aircraft and that the inspections are fully carried out.
22 ) ) ) ) SECONDARY CAUSE OR CONTRIBUTING FACTORS: 26. Collision in the air.	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  CONCLUSIONS OF A.I.B. (891)  From the evidence produced F/S Gaskin could be given the benefit of a doubt and it appears that the wires were broken without his knowledge when the A/C came out of the spin at low altitude.
) D. COIIISION IN the air.	RECORDED BY DATE
) R.C.A.F. FORM LZO REQ. 1247 10M-15-11-41	CHECKED BY DATE